

**From:**

SERVICE FIRST HVAC SOLUTIONS CO.

721 Amsterdam St.

Woodstock, IL 60098

ServicePro@servicefirstusa.com

24/7 Dispatch: +1 (866)922 2580

Invoice Number	INV-2559
Invoice Date	December 27, 2021
Due Date	January 6, 2022
Total Due	\$0.00

To:

Anodyne Corporation

1136 Rose Rd Lake Zurich, Illinois 60047

Service@anodynecorp.net

PO/ TRACKING # 35784

Service Urgency: Regular (24 to 48 hrs)

Service Type: Service Repair

Job description: Inspect unit for leak & add Freon if needed.

Job Address: Lifescan Laboratory Inc
5255 Golf Rd
Skokie, Illinois 60077

Equip. Model- MBF8005

All invoices are due according to the terms shown on your invoice, All cancellations are subject to restocking charges for up to 30% of the total of the invoice and special orders shipping and labor charges are not refundable.



- FOUND COMPRESSOR OVERHEATING AND SHUTTING OFF
 RECOMMENDATIONS; REPLACE COMPRESSOR- A QUOTE WILL FOLLOW.
 NOTES; COOLER MUST BE EMPTY TO PERFORM THIS JOB.

Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
1.5	TECH TIME	\$185.00	0%	\$277.50
1	Travel/Truck Charge	\$35.00	0.00%	\$35.00

Sub Total	\$312.50
Tax	\$0.00
Paid	-\$312.50
Total Due	\$0.00

To pay by check, Make checks payable to
 Service First HVAC Solutions Co.

For credit card payments:
<https://www.servicefirstusa.com/credit-card-authorization/>

Payment is due within 10 days from the date of invoiced. Late payment is subject to fees of 5% per month.

All invoices are due according to the terms shown on your invoice, All cancellations are subject to restocking charges for up to 30% of the total of the invoice and special orders shipping and labor charges are not refundable.